



LC1 F115...F1250


www.schneider-electric.com




LC1 F115
LC1 F150
LC1 F185
LC1 F225
LC1 F265
LC1 F330



LC1 F400
LC1 F500



LC1 F630
LC1 F800



LC1 F1250

"For Motor Starting Use Schneider Electric Overload Relay Series LR"



DANGER / DANGER / PELIGRO / GEFAHR / PERICOLO / PERIGO / 危险 / ОПАСНО

**HAZARD OF ELECTRIC SHOCK, EXPLOSION,
OR ARC FLASH**
Disconnect all power before servicing equipment.

Failure to follow these instructions will result in
death or serious injury.

**PELIGRO DE DESCARGA ELÉCTRICA, EXPLOSIÓN
O ARCO ELÉCTRICO**
Desconecte todas las alimentaciones antes
de manipular el producto.
Si no se siguen estas instrucciones provocará
lesiones graves o incluso la muerte.

**RISCHIO DI SCARICA ELETTRICA, ESPLOSIONE
O ARCO ELETTRICO**
Scollegare l'apparecchio da tutti i circuiti di
alimentazione prima di qualsiasi intervento.
Il mancato rispetto di queste istruzioni provocherà
morte o gravi infortuni.

可能有触电、爆炸或者电弧灼伤的危险
在此电力设备上工作时, 请先切断所有电源
若违背这些说明,
不遵循上述说明将导致人员伤亡。

**RISQUE D'ÉLECTROCUTION, D'EXPLOSION OU
D'ECLAIR D'ARC ÉLECTRIQUE**
Coupez toutes les alimentations avant de travailler
sur cet appareil.

Le non-respect de ces instructions provoquera
la mort ou des blessures graves.

**GEFAHR VON ELEKTRISCHEM SCHLAG,
EXPLOSION ODER LICHTBOGEN**
Vor dem Arbeiten am Gerät alle
Spannungsversorgungen abschalten.
Die Nichtbeachtung dieser Anweisungen führt
zu Tod oder schwereren Verletzungen.

**RISCO DE ELECTROCUSSÃO, DE EXPLOÇÃO,
OU DE ARCO ELÉCTRICO**
Desconecte todas as alimentações antes de manipular
o produto.
A não observância destas instruções resultará em
morte, ou ferimentos graves.

Опасность поражением электрическим током,
опасность взрыва или вспышки дуги.
Перед обслуживанием или ремонтом
убедитесь, что питание отключено.
Несоблюдение этих инструкций приведет
к смерти или серьезной травме.