



Connection terminals and interfaces

PXC....D



PXC....E.D



1, 2	24 V ~, ⊥	Operating voltage AC 24 V	Plug-in screw terminal block
3	⏏	Functional ground	
(A)	USB	USB host interface (for modem via PXA-C3 adapter cable)	
4, 5 (B)	CLA, CLB	LONWORKS bus	Plug-in screw terminal blocks
(C)	HMI	RJ45 interface (LONWORKS) for operator unit PXM20 (tool as well)	
(D)	RJ45	RJ45 interface for Ethernet (Operator unit PXM20-E can be connected to hub/switch)	
(E)	HMI / Tool	RJ45 interface (LONWORKS and serial) for PXM10, PXM20 and tool	
(F)	USB	USB device interface (for future applications)	
(G)	HMI	RJ45 interface (serial) for operator unit PXM10	