

## Preparing the Environment

Ensure that the environment in which you are using the NI 9234 meets the following specifications.

|                                                         |                                    |
|---------------------------------------------------------|------------------------------------|
| Operating temperature<br>(IEC 60068-2-1, IEC 60068-2-2) | -40 °C to 70 °C                    |
| Operating humidity<br>(IEC 60068-2-78)                  | 10% RH to 90% RH,<br>noncondensing |
| Pollution Degree                                        | 2                                  |
| Maximum altitude                                        | 5,000 m                            |

Indoor use only.



**Note** Refer to the device datasheet on [ni.com/manuals](http://ni.com/manuals) for complete specifications.